



Start Instructions

- 1) Press the power button  and wait for the display to show zero.
- 2) Press the “Unit” button to shift between “gn” (grains) or “g” (grams).
- 3) Press the “Tare” button to zero the scale.

Calibration Instructions

- 1) Start the scale as described above.
- 2) Press and hold the power button  for 3 seconds until the display shows “-0-”
- 3) The display will then flash “50.00” g.
- 4) Place the supplied 50-gram weight on the scale and wait for the “50.00” to stop flashing.
- 5) Calibration is complete.
- 6) Remove the weight and select the desired unit, “gn” or “g” with the Unit button.
- 7) Place the powder pan on the scale and press “Tare” to zero it.
- 8) The scale is ready to weigh powder.

Charging the Scale

When the scale indicates a low battery condition, connect the scale to any cell phone charger. The three ports are compatible with Micro USB, USB Type C and Lightning plugs. Charging will be complete in about 2 hours.